

OK PR: 1 PLUTO10 T%: 10% S: 600rpm J:S

Screw: 01/02 Seq: 1/1 T: 1.26 Nm 24/03/14

08:38:51

OK PR: 1 PLUTO10 T%: 10% S: 600rpm J:S

Screw: 02/02 Seq: 1/1 T: 1.28 Nm 24/03/14

08:38:54 Program end

EC
110 23/03/2004 08:31 +01.83 Nm < 00.4 S

EC

111 23/03/2004 08:31 +01.50 Nm < 00.4 S

EC

112 23/03/2004 08:31 +01.44 Nm < 00.4 S

EC

113 23/03/2004 08:31 +01.28 Nm < 00.4 S